

EVALUATION OF SUPERHARD TRANSPARENT COATINGS

DDC FILE COPY

JOHN R. PLUMER COMPOSITES DIVISION

February 1978



Approved for public release; distribution unlimited.

ARMY MATERIALS AND MECHANICS RESEARCH CENTER Watertown, Massachusetts 02172

The findings in this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

Mention of any trade names or manufacturers in this report shall not be construed as advertising nor as an official indorsement or approval of such products or companies by the United States Government.

DISPOSITION INSTRUCTIONS

Destroy this report when it is no longer needed.

Do not return it to the originator.

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
AMMRC—TR—78-10	NO. 3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitie)	TYPE OF REPORT & PERIOD COVERED
EVALUATION OF SUPERHARD TRANSPARENT COATINGS.	Final Report
7. AUTHOR(a)	8. CONTRACT OR GRANT NUMBER(s)
John R. Plumer	
9. PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM EL FAFAT, PROJECT, TASK
Army Materials and Mechanics Research Center Watertown, Massachusetts 02172 DRXMR-RD	D/A Project: 1F262209AH76D4 AMCMS Code: 622209.12.H7604
Eustis Directorate, U. S. Army Air Mobility Research and Development Laboratory, Fort Eustis, Virginia 23604	February 1978 13. NUMBER OF PAGES 11
14. MONITORING AGENCY NAME & ADDRESS(II dil'erent from Controlling Office) 15 SECURITY CLASS. (of this report)
Army Materials and Mechanics Research Center Watertown, Massachusetts 02172	Unclassified 15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlim	
Approved for public release; distribution unlim	trom Report)
Approved for public release; distribution unlim	ited.
Approved for public release; distribution unlim 17. DISTRIBUTION STATEMENT of the observed entered in Block 20, if different 18. SUPPLEMENTARY NOTES	rited.
Approved for public release; distribution unlim 17. DISTRIBUTION STATEMENT of the observed entered in Block 20, if different 18. SUPPLEMENTARY NOTES 19. KEY WORDS (Continue on reverse side if necessary and identify by block number Composites Abrasion coating Polycarbonate Acrylics	rited.
Approved for public release; distribution unlim 17. DISTRIBUTION STATEMENT of the obstract entered in Block 20, if different 18. SUPPLEMENTARY NOTES 19. KEY WORDS (Confinue on reverse side if necessary and identify by block number Composites Abrasion coating	trom Report) 1978
Approved for public release; distribution unlim 17. DISTRIBUTION STATEMENT of the securical entered in Block 20, if different 18. SUPPLEMENTARY NOTES 19. KEY WORDS (Continue on reverse side if necessary and identify by block number of the continue on cont	trom Report) 1978
Approved for public release; distribution unlim 17. DISTRIBUTION STATEMENT of the evertect entered in Block 20, if different 18. SUPPLEMENTARY NOTES 19. KEY WORDS (Continue on reverse side if necessary and identify by block number of the continue on conti	trom Report) 1978
Approved for public release; distribution unlim 17. DISTRIBUTION STATEMENT to the evertee entered in Block 20, if different 18. SUPPLEMENTARY NOTES 19. KEY WORDS (Continue on reverse side if necessary and identify by block numb Composites Abrasion coating Polycarbonate Acrylics As-cast acrylic 20. ABSTRACT (Continue on reverse side if nocessary and identify by block numb	trom Report) 1978

DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE

A CONTROLL OF THE PROPERTY OF

UNCLASSIFIED

403 SECURI Y CRASSIFICATION OF THIS PAGE (When Date Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Date Entered)


Block No. 20

ABSTRACT

A test program was carried out to assess hard surface coatings developed for reducing scratching problems encountered with plastic glazings used in Army aircraft.

The tests employed simulated aircraft flight and handling conditions, and consisted of the following: a windshield wiper test, a felt-pad abrader test, solvent resistance, hardness, impact, ultraviolet exposure, humidity, and weatherometer testing.

The coatings were found to substantially increase the abrasion resistance of several types of plastic materials; water and ultraviolet radiation were factors adversely affecting coating performance.



UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

INTRODUCTION

The majority of Army helicopters currently use an acrylic plastic as a glazing material; however, recent combat service has demonstrated these windshields are extremely prone to scratching (due to wiper blade action and propwash blown dust) and require frequent replacement. Acrylic glazing also produces potentially dangerous spall on foreign object impact (e.g., blown rocks, small arms fire). Previous work has shown that polycarbonate plastic, coated with a protective hard-surface material, offers a solution to spallation, while the hard surface coating significantly increases the resistance to surface-produced abrasion. The feasibility of coated polycarbonate UH-1 helicopter windshields has been demonstrated through flight testing. Typical available coatings, however, afford protection for a limited time as most are susceptible to extremes of sunlight and humidity.

The objective of this test program is to evaluate the performance, in a simulated windshield regime, of a unique concept of hard surface coating developed for transparent plastic. The "Super Hard Transparent Coatings" were developed and applied to specimens used in this effort by Marks Polarized Corporation, Whitestone, New York, under Eustis Directorate, USAAMRDL Contract DAAJ02-73-C-0062. This contract represents part of a concerted effort by AVRADCOM to upgrade the performance and reliability of transparencies on all classes of Army aircraft. The testing phase of the program was established with AMMRC specifically to duplicate the tests that were described in the contractor's test plan in order to substantiate and verify independently the contractor's test results. Additional tests were performed to complete the evaluation of the candidate materials, Super Hard Transparent Coatings, for possible use in Army aircraft windshields.

MATERIALS

The coatings under investigation, 129c (70% silica, 30% polyvinyl alcohol) and 130 (15% aluminum oxide, 70% silica, 15% polyvinyl alcohol), were applied to the following plastics: polycarbonate, Plex II, and stretched acrylic. These coatings employ a transparent polymer (or coating) containing hard submicron particles held in suspension. The submicron particles do not appreciably scatter light because of their small size (diameter of approximately 100 Å).

TESTING INSTRUMENTATION AND PROCEDURE

Abrasion Resistance

The ability of a transparent polymer to withstand mechanical and nonmechanical abrasion, with a minimal loss of optical properties, is of fundamental interest. Abrasion resistance of a transparent polymer may then be determined

1. PLUMER, J. R. Development of Scratch and Spall-Resistant Windshields. Army Materials and Mechanics Research Center, AMMRC TR 74-19, August 1974.

by quantitatively measuring the haze produced by a given test method. For materials such as polycarbonate, acrylic, and stretched acrylic, the scratch resistance of coatings is a necessary determination when considering aircraft applications.

The problem of evaluating plastics and coatings for abrasion resistance was approached by utilizing a test apparatus designed to simulate field conditions. A windshield wiper test apparatus was used to approximate in-flight effects on windshields. The apparatus shown in Figure 1 allowed control of such variables as wiper speed, abrasive, arm pressure, and monitoring of the test conditions.




Figure 1. Windshield wiper apparatus. 19-066-632/AMC-76

TENTONICHERANDEN BEGINNER SENENDER SENE

Windshield Wiper Test

All samples were cut to a size of 6" x 6" and flush fitted into a mask for mounting. The abrasive slurry used for all testing consisted of A.C. air cleaner test dust, coarse (50% 30 to 80 micron) size, continuously suspended in solution by a mechanical stirrer. The slurry contains 300 grams of grit per three liters of water. Flow rate was regulated at approximately 300 ml per minute and

discharged between samples. Cycle speed was maintained at 100 cycles per minute, the approximate low speed of a UH-1 helicopter, while wiper load was fixed at six pounds. After every 1000 cycles samples and control were removed from the testing table, rinsed and dried, and evaluated for light and haze transmission as described in ASTM D1003-61. A Hunter Lab color-color difference meter (model D250P2) was used for light conversion and haze determination throughout the test program. Results are listed in Table 1.

Table 1. ABRASION RESISTANCE WINDSHIELD WIPER TEST

		Polycarbonate				Plex II					Stretched Acrylic							
	Unco	ated	129	С	13	0	Unco	ated	12	9c	13	0	Unco	ated	12	9c	13	0
Cycles	%T	#H	%T	%Н	%Т	%Н	%Т	%н	ХT	%Н	ХT	%Н	%Т	%н	%T	%Н	%T	%H
0	87.7	1.2	89.4	1.2	89.4	1.2	93.8	0.70	93.2	0.64	93.2	0.64	97.0	0.80	93.6	0.84	93.1	1.1
500	84.0	15.3	89.2	3.8	89.0	2.2	91.5	20.0	93.3	0.93	92.6	2.1	92.5	18.5	92.9	1.1	93.0	1.7
1,000	84.0	21.0	89.2	5.8	89.0	2.8	89.6	23.5	93.0	1.2	91.3	2.7	90.5	21.5	92.2	1.9	92.9	2.1
2,000	-	-	89.0	6.0	88.6	3.3	-	-	93.2	1.2	91.2	2.6	-	-	91.9	1.9	92.9	2.1
3,000	~	-	89.0	6.1	88.0	5.3	_	-	93.2	1.2	91.1	2.6	-	_	91.2	2.2	91.9	3.1
4,000	-	-	89.0	6.1	88.4	5.1	-	-	91.5	1.9	91.1	2.5	-	-	91.0	2.4	91.5	3.5
5,000	-	-	89.0	6.4	88.3	5.6	-	_	91.3	2.2	89.8	2.5	-	-	90.6	2.5	91.5	3.5
6,000	_	-	88.9	6.7	88	6.4	-	_	91.0	2.4	89.5	2.9	-	-	90.4	2.8	91.2	3.8
7.000	-	-	88.7	7.5	88.3	6.7	-	-	90.9	2.3	89.5	3.0	-	-	90.1	2.9	91.0	3.9
8,000	-	-	88.6	7.0	87.7	6.6	-	-	90.5	2.5	89.2	3.3	-	-	89.8	3.9	89.8	4.0
9,000	~	-	87.9	7.3	87	6.7	-	-	90.7	2.2	89.0	3.2	-	-	89.8	3.0	89.7	4.4
10,000	_	-	87.8	7.8	87	6.8	-	-	90.6	2.5	89.0	3.7	-		88.1	2.2	89.1	4.5

All values represent an average of 3 test runs per sample

Temperature at time of testing 72 F, 35% RH

%T = % Transmission

%H = % Haze

Reciprocating Arm Felt Pad Abrader

Evaluation of abrasion effects were also made by using a reciprocating arm felt pad abrader, designed to approximate conditions encountered by field cleaning of helicopter windshields by aircraft personnel, Figure 2. This unit provides an approximation of the nonmechanical cleaning action, such as hand wiping by the crew, of a windshield during operation of the helicopter. This unit is preferred over the Taber abrader because the abrasive area is larger, 1" x 2", and is designed to fit the inspection area exactly in the Hunter Lab Optical Head.




Figure 2. Reciprocating arm felt pad abrader. 19-066-631/AMC-76

All samples were cut to a uniform size, 6" x 6", permitting the samples to be precisely refitted into the optical head and the abrader unit. A one-inch-diameter disk, 100% wool felt 1/8" thick, was cemented to the abrader head. The reciprocating speed was maintained at 50 cycles per minute; a 500-gram load was applied to the head during testing. Samples were placed into the unit with their coated side facing the abrader head. The felt pad was impregnated with 60 grit Norbide boron carbide abrasive and placed in the unit, this being repeated after every 100 cycles. Samples were removed after every 100 cycles and all abrasive material was removed from the evaluating area. Optical properties were then measured. Tests were continued until 10% haze or 1000 cycles were reached. Results are given in Table 2.

Table 2. ABRASION RESISTANCE, FELT PAD RECIPROCATING ARM ABRADER

	Polyca	rbonat	e _	P1e	x II		Stretched Acrylic			
Cycles	Uncoated	129c	130	Uncoated	129c	130	Uncoated	129c	130	
0	2.8	1.3	1.6	1.3	1.1	1.8	1.7	1.7	1.6	
1	9.9	-	-	-	-	-	-	_	-	
2	13.1	-	-	-	-	-	-	_	•	
2 3 4 5 6	16.7	-	-	-	-	-	-	-	-	
4	22.1	-	-	-	-	-	-	-	_	
5	23.1	_	-	12.9	-	-	12.8	-	_	
6	28.7	-	_	_	-	_	-	_	-	
10	_	-	_	17.1	-	-	17.1	-	-	
15	-	_	_	19.5	-	-	22.0	-	-	
20	-	-	_	25.2	-	_	27.0	-	-	
100	•	1.7	2.3	-	1.4	2.2	-	1.8	2.1	
200	-	1.9	3.1	_	1.5	2.6	-	2.2	2.7	
300	-	2.0	3.5	-	2.7	3.0	_	2.0	3.2	
400	-	2.8	3.7	-	2.4	3.4	-	2.1	3.3	
500	_	4.0	3.9	_	2.5	4.2	-	2.2	3.3	
600	_	4.4	4.6	-	2.7	3.8	_	2.4	3.6	
700	-	4.2	5.9	-	2.9	4.6	-	2.6	3.8	
800	_	4.8	5.9	_	3.0	4.7	_	2.8	4.1	
900	-	5.1	6.3	-	3.4	5.5	-	2.9	4.2	
1,000	-	5.4	7.5	-	3.5	5.6	-	3.4	4.2	

All values are given in percent haze, ASTM 1000-3

Solvent Resistance

The coated side of each transparent polymer was subjected to 15 minutes of exposure to the following solvents:

dell'e strangent de la constance de la contracte de la contrac

Methyl Ethyl Ketone	Toluene	Methyl Alcohol
Methyl Isobutyl Ketone	Hexane	Butyl Alcohol
Acetone	Xylene	Isopropyl Alcohol

An eyedropper was used to aid in dispensing solvents uniformly. After exposure they were rinsed and dried, and their optical properties, light transmission and haze transmission, were measured. Results are listed in Table 3.

Mohs' Hardness

The Mohs' hardness scale was used to assess hardness of the coated plastic samples. The scale determines hardness by comparison of test materials with natural minerals. For a given Mohs' hardness, rutbing two materials any number of

Table 3. SOLVENT TESTING* OF SUPERHARD TRANSPARENT COATINGS

	Pol	ycarbonat	e	Plex II				
Solvents Solvents	Uncoated	129c, %	130, %	Uncoated	129c, %	130, %		
None	1.3%	1.3	1.5	0.7%	0.7	1.3		
Hexane	No Effect	1.6	1.6	No Effect	1.4	2.0		
Xylene	Severe Blistering [†]	2.2 Crazing	14.4 Severe Crazing	Slight Crazing	0.85	1.6		
Toluene	Severe Blistering [†]	4.7 Crazing	32.4 Severe Blistering	Slight Crazing	0.85	2.0		
Acetone	Blistering	4.0 Slight Crazing	10.4	Clouding	0.75	2.6		
Butyl Alcohol	No Effect	1.6	1.5	No Effect	0.1	2.2		
Isopropyl Alcohol	No Effect	3.6	3.0	No Effect	1.7	3.6		
Methyl Alcohol	No Effect	1.8	1.5	Slight Crazing	0.85	1.8		
Methyl Isobutyl Ketone	Ground Glass Look Effect [†]	3.5	3.4	Slight Crazing	0.9	1.3		
Methyl Ethyl Ketone	Severe Blistering	2.2	10.4 Severe Crazing	Ground Glass Look Effect†	0.9	2.0		

^{*}All numerical data is represented as percent haze. All optical measurements were conducted with the coated side of the sample facing the light source. †Some tests produced haze too extreme to accurately determine.

cycles or at any pressure will not produce visible scratching if the Mohs' hardness of the material exceeds that of the abrasive (mineral). All tests were conducted on the coated side of the sample. The results show that all samples have a Mohs' hardness of approximately 3.5 to 4.0. The scale used consisted of the following minerals (the number identifies the Mohs' hardness value): 1. Talc; 2. Gypsum; 3. Calcite; 4. Fluorite; 5. Apatite; 6. Feldspar; 7. Quartz; 8. Beryl.

Accommendation of the control of the

Impact Testing

Impact testing was conducted in accordance with the method outlined in the contractor's test plan. A 200-gram steel ball was dropped from a height of 50 cm, utilizing a Visoteck Model FD 9150 impact test apparatus, after which the sample was evaluated for any apparent fracture or separation of the coating from the substrates. Samples of 129c and 130 coatings on Plex II, polycarbonate, and stretched acrylic were tested; none of the samples suffered any apparent fractures or separation of the coatings from the substrate.

Ultraviolet Testing

A temperature-controlled aging chamber equipped with an ozone-generating ultraviolet lamp (8 watts over a range of 2537 Å through 4360 Å) was used for the test. Samples were positioned with the coated side toward the lamp and six inches from the source. Chamber temperature was maintained at 75 C. Samples

were removed and inspected for crazing and haze development on an hourly basis for the first eight hours of the test cycle, and every 24 hours for the full duration of the 120-hour test. In general, this accelerated regime is about seven times more severe than outdoor exposure at a hot-dry site. This test method is based on procedures outlined in MIL-STD-810-D. The results of exposure and abrasion testing are shown in Table 4.

Ultraviolet Uncoated PC* Exposure Stretched Acrylic Plex II Radiation Plex II 129c 129c 129c **Effect** Day Hour 130 No Change Cracking Cracking 1 6 Cracking Cracking 32 2 3 4 56 80 104 120 Post Exposure, Felt Pad ZН хн %T хн %T 2н Abrasion Test Cycles **LT** 93.0 1.39 0 93.0 88.7 89.7 2,00 89.3 2.0 88.7 Values Unchanged 85.2 2.8 200 92.5 1.29 88.6 3.0 89.6 2.56 400 from Table 1 90.3 2.76 92.0 1.84 87.1 3.8 83.6 91.0 2.08 4.0 83.1 4.7 600 89.8 3.00 87.1 89.7 3.34 90.0 3.22 81.5 800 87.6 4.6 90.5 3.20 1000 86.0 5.9 81.2 1200 90.2 3.43

Table 4. ULTRAVIOLET EXPOSURE AND ABRASION TESTING

Water Immersion Test

Samples were submerged in distilled water maintained at 70 F; periodic removal, air drying, and inspection was made to determine any development of microcracking, haze, or deterioration of the coating surface. A felt-pad abrasion test was conducted at the conclusion of the 48-hour immersion test. Some results of the testing are shown in Table 5. Polycarbonate coated with 130 showed both a very rapid development of microcrazing (less than one hour) and a significant reduction in abrasion resistance. Twice as much haze developed on the water-soaked samples as was produced by similar testing on virgin coated (130) polycarbonate.

ing in the companies of the contraction of the cont

Cracking developed on the 129c polycarbonate after 16 hours of water immersion; however, abrasion resistance was decreased only slightly. The optical properties of all samples appeared unchanged by the water immersion. No significant change was noted in abrasion properties on the Plex II coated samples.

^{*}Polycarbonate

A test program was carried out to assess hard surface coatings developed for reducing scratching problems encountered with plastic glazings used in Army aircraft. The tests employed simulated aircraft flight and handling conditions, and consisted of the following: a windshield wiper test, a fell-pad abrader test, solvent resistance, hardness, impact, ultraviolet exposure, hundity, and weatherometer testing. The coatings were found to substantially increase the abrasion resistance of several types of plastic materials; water and ultraviolet radiation were factors adversely affecting coating performance. A test program was carried out to asses, hard surface coatings developed for reducing scratching problems encountered with plastic glazings used in Army aircraft. The tests employed simulated aircraft flight and handling conditions, and consisted of the following: a windshield wiper test, a felt-pad abrader test, soluter resistance, hardness, impact, ultraviolet exposure, humidity, and weatherometer testing. The coatings were found to substantially increase the abrasion resistance of several types of plastic materials; water and ultraviolet radiation were factors adversely affecting coating performance. UNCLASSIFIED UNLIMITED DISTRIBUTION UNCLASSIFIED UNLIMITED DISTRIBUTION As-cast, acrylic As-cast acrylic **Polycarbonate** Polycarbonate Key Words **Key Words** Composites Composites 됳 đ 윱 Technical Report AWMRC TR 78-10, February 1978, 11 illus-tables, D/A Project 1F262209AH7604, AMCMS Code 622209.12.H7604 Technical Report AWMRC TR 78-10, February 1978, 11 illus-tables, D/A Project 1F262209AH7604, AMCMS Code 622209.12.H7604 Materials and Mechanics Research Center, Watertown, Massachusetts 02172 EVALUATION OF SUPERHARD TRANSPARENT COATINGS John R. Plumer Watertown, Massachusetts 02172 EVALUATION OF SUPERHARD TRANSPARENT COATINGS John R. Plumer Materials and Mechanics Research Center. Watertown, Massachusetts 02172 Army Army A test program was carried out to assess hard surface coatings developed for reducing scratching problems encountered with plastic glazings used in Army aircraft. The tests employed simulated aircraft flight and handling conditions, and consisted of the following: a windshield wiper test, a fell-pad abrader test, solvent resistance, hardness, impact, ultraviolet exposure, humdity, and weatherometer testing. The coatings were found to substantially increase the abrasion resistance of several types of plastic materials: water and ultraviolet radiation were factors adversely affecting coating performance. A test program was carried out to assess hard surface coatings developed for reducing scratching problems encountered with plastic glastings used in Army aircraft. Inte tests employed simulated aircraft filght and handling conditions, and consisted of the following: a windshield wiper test, a felt-pad abrader test, solvent resistance, hardness, impact, ultraviolet exposure, humidity, and weatherometer testing. The coatings were found to substantially increase the abrasion resistance adversel types of plastic materials; water and ultraviolet radiation were factors adversely affecting coating performance. UNCLASSIFIED UNLIMITED DISTRIBUTION UNCLASSIFIED UNLIMITED DISTRIBUTION carried out to assess hard surface coatings developed for re-Composites Polycarbonate As-cast acrylic Polycarbonate As-cast acrylic Key Words Key Words Composites 飠 Technical Report AMMRC TR 78-10, February 1978, 11 pp illus-tables, D/A Project 1F262209AH7604, ANCMS Code 622209.12.H7604 8 iscal Report AWMRC TR 78-10, February 1978, 11 flus-tables, D/A Project 1F262209AH7604, AMCMS Code 622209.12.H7604 Materials and Mechanics Research Center, Watertown, Massachusetts 02172 EVALUATION OF SUPERHARD TRANSPARENT COATINGS Materials and Mechanics Research Center, Watertown, Massachusetts 02172 EVALUATION OF SUPERHARD TRANSPARENT COATINGS Technical Report AMMRC John R. Plumer John R. Plumer ¥ ATT

one many control of the control of t

Table 5. WATER IMMERSION (70 F) AND ABRASION TESTING

Hours of	Po1yca	rbonate	Plex II				
Immersion	129c	129c 130		130			
1	Unchanged	Microcracking	Unchanged	Unchanged			
2	1	ı	ı	1			
3							
4			ļ				
8	†	ì	ì]			
16	Microcracking			ļ			
24	1	1	Ĩ	Ì			
32		!		ļ			
40		l		i			
48	\	₩		₩			

Felt Pad Abrasion Tests, 48 hr of Water Immersion

Cycles	%Т	%H	%T	%H	%T	%Н	%Т	%;;
0 200 400 600 800 1000	89.0 82.8 82.4 78.0 74.0 66.8	3.2 7.0 5.75 9.9 14.4 14.9	88.8 85.9 85.2 84.6 83.0 86.9	2.7 4.3 4.8 6.0 7.9	89.3 89.9 87.2 86.4 85.5 85.0	4.5 5.4	80.4 85.1 83.4	12.1

Weatherometer Evaluation

Weatherometer testing was conducted using an Atlas weatherometer located at Natick Laboratories, Natick, MA. Simulated radiant sunlight (Xenon light source) was continuously maintained on a 12-hour light - 12-hour dark cycle for the total experimental run of 300 hours, i.e., the approximate equivalent to six months of outdoor exposure in a temperate climate. Temperature was maintained at 100 F; humidity was maintained at 50% RH, throughout the 300-hour test. This procedure is essentially as described in the FTM 406, method 6024. Samples of the two coatings were subjected to this exposure test; optical properties before and after testing are shown in Table 6. Samples were examined at the conclusion of the testing for cracking, crazing, or bubbling of the coating. Both coatings developed extensive cracking; the cracking on the 130 Plex II sample was, by far, the

Table 6. ACCELERATED WEATHEROMETER TEST

Atlas Weathermeter Chamber; Exposure 300 hr at 100 F, 50% RH, 12-hr Irradiation Cycle

Abrasion Resistance % Haze at 1000 Cycle, Felt and Abrader and the contraction of the contr

Company of the continues of the continues of

				Tere and	ADIAGE	
	%Н	Total Light Transmission	Yellowness Index	%н	%Т	Comments
Plex II 130	1.8	93.1	-2.1	5.6	89.5	Optically Clear
Plex II 129c	1.1	93.4	-2.2	3.5	91.0	
Post 300 hr Exposure						
Plex II 130	2.6	93.7	-1.5	6.4	86.4	Severe Crazing after Exposure
Plex II 129c	1.7	93.1	-1.9	4.0	91.6	Crazing

more extensive, while the 129c Plex II sample crazed in a loose "spider web" pattern. Felt pad abrasion tests were run on the exposed samples. The results are compared to test values for virgin materials in Table 6. No bubbling or delamination of either coating was noted; nor was there any significant change in the abrasion resistance of either coating.

DISCUSSION

It may be concluded, based on assessment of the results of both abrasion tests, that the coating systems provide a significant improvement in the abrasion resistance of polycarbonate and acrylic plastics. The relative improvement achieved by the addition of the coatings to various substrate plastics is generally comparable or superior to other coating systems evaluated in previous studies. It is felt this coating system offers promise in windshield application if significant improvements can be obtained in environment resistance and if commercial availability is achieved. It is recommended that further work be carried out to optimize these coatings.

Marks' coatings, when tested dry with the pad abrader, are at least four times superior in abrasion resistance to Abcite-coated polycarbonate (see Reference 1). The coating appears to be susceptible to ultraviolet and humidity conditions. Testing with a simulated and accelerated outdoor regime produces extensive and visually distracting microcracking; however, it does not appear to seriously affect abrasion resistance. It may be assumed that UV radiation was the primary factor producing the observed cracking. A possible mechanism would be the UV radiation affecting main-chain breakage of the PVA matrix; stresses within the coating (possibly at sites of microparticle inclusions) would subsequently cause the cracking. Microcracking, in all samples tested, occurred only in the coating, with no change noted in any of the substrates. (This observation is based on a discussion with Dr. R. Sacher, AMMRC.)

Similar cracking was also observed on post-test inspection of samples exposed to UV radiation alone. This is similar to that produced by the weatherometer testing and, similarly, no significant loss of abrasion resistance was noted.

Humidity, however, appears to cause a decrease in intermolecular bond strength within the PVA matrix, resulting in the coatings becoming softer and significantly less abrasion resistant. This was demonstrated by the abrasion test carried out on the "water soak" samples. The water soak samples were abrasion tested immediately on removal from the water bath (i.e., the PVA was infiltrated by water) resulting in about twice the haze development normally encountered by this test. The presence of water either during testing (windshield wiper test) or immediately preceding it (water soak test) was found to adversely affect the abrasion resistance of the 129c coating when applied to polycarbonate; this was witnessed by the 130 coating on polycarbonate giving superior abrasion resistance only in those two tests involving water while yielding inferior performance to the 129c coating with the remaining test methods. A possible explanation for this reversal of coating performance is the greater hydrophilicity of the polycarbonate over acrylic plastic. This would result in poorer surface adhesion with a PVA coating to the hydroscopic surface than to the relatively

"drier" acrylic surface. For all dry abrasion tests, surface adhesion becomes less influential in affecting coated performance; this results in the coating having the greater particulate material (130) giving the superior abrasion resistance.

Solvent testing of the coated plastic materials produced crazing on several of the coated polycarbonate samples; it was assumed that this crazing was due to solvent reaction with the polycarbonate plastic occurring through voids in the coating. This is the most logical explanation for the crazing reaction as PVA is soluble only in water or water and phenol. The particulate filler in the coatings is insoluble and unaffected by any of the organic solvents used in this test; therefore, the only reaction possible is between the test solvent and the substrate plastic materials.

Insufficient stretched acrylic materials were provided for inclusion in all the test methods. The only tests performed on this material were those which were judged most useful in assessing the performance of the coated plastic.

DISTRIBUTION LIST

No. of Copies

To

- 1 Office of the Director, Defense Research and Engineering, The Pentagon, Washington, D. C. 20301
- 12 Commander, Defense Documentation Center, Cameron Station, Building 5, 5010 Duke Street, Alexandria, Virginia 22314
- 1 Metals and Ceramics Information Center, Battelle Columbus Laboratories, 505 King Avenue, Columbus, Ohio 43201

Office of the Deputy Chief of Staff for Research, Development, and Acquisition, Washington, D. C. 20310

2 ATTN: DAMA-ARZ

Commander, Army Research Office, P. O. Box 12211, Research Triangle Park, North Carolina 27709

1 ATTN: Information Processing Office

Commander, U. S. Army Materiel Development and Readiness Command, 5001 Eisenhower Avenue, Alexandria, Virginia 22333

1 ATTN: DRCLDC, Mr. R. Zentner

Commander, U. S. Army Electronics Research and Development Command, Fort Monmouth, New Jersey 07703

1 ATTN: DRDCO-GG-DD 1 DRDCO-GG-DM

Commander, U. S. Army Missile Research and Development Command, Redstone Arsenal, Alabama 35809

MINIMER CHEEF CONTRACTOR OF THE FOREST CONTRACTOR OF THE SECOND CONTRACTOR CONTRACTOR OF THE SECOND CONTRACTOR OF THE SEC

1 ATTN: DRDMI-RKK, Mr. C. Martens, Bldg. 7120

Commander, U. S. Army Armament Research and Development Command, Dover, New Jersey 07801

2 ATTN: Technical Library

1 DRDAR-SCM, Mr. J. D. Corrie

Commander, U. S. Army Natick Research and Development Command, Natick, Massachusetts 01760

1 ATTN: Technical Library

Commander, U. S. Army Satellite Communications Agency, Fort Monmouth, New Jersey 07703

1 ATTN: Technical Document Center

Commander, U. S. Army Tank-Automotive Research and Development Command, Warren, Michigan 48090

2 DRDTA-UL, Technical Library

Commander, White Sands Missile Range, New Mexico 88002

1 ATTN: STEWS-WS-VT

Commander, Aberdeen Proving Ground, Maryland 21005

1 ATTN: STEAP-TL, Bldg. 305

President, Airborne, Electronics and Special Warfare Board, Fort Bragg, North Carolina 28307

1 ATTN: Library

Commander, Dugway Proving Ground, Dugway, Utah 84022

1 ATTN: Technical Library, Technical Information Division

Commander, Frankford Arsenal, Philadelphia, Pennsylvania 19137

1 ATTN: Library, H1300, B1. 51-2

Commander, Harry Diamond Laboratories, 2800 Powder Mill Road, Adelphi, Maryland 20783

1 ATTN: Technical Information Office

Commander, Picatinny Arsenal, Dover, New Jersey 07801

1 ATTN: SARPA-RT-S

Commander, Redstone Scientific Information Center, U. S. Army Missile Research and Development Command, Redstone Arsenal, Alabama 35809

The second of th

1 ATTN: DRDMI-TB

Commander, Watervliet Arsenal, Watervliet, New York 12189

1 ATTN: SARWV-RDT, Technical Information Services Office

Commander, U. S. Army Foreign Science and Technology Center, 220 7th Street, N. E., Charlottesville, Virginia 22901

1 ATTN: Mr. Marley, Military Tech

Commander, U. S. Army Aeromedical Research Unit, P. O. Fox 577, Fort Rucker, Alabama 36460

1 ATTN: Technical Library

Director, Eustis Directorate, U. S. Army Air Mobility Research and Development Laboratory, Fort Eustis, Virginia 23604

1 ATTN: Mr. J. Robinson, DAVDL-E-MOS (AVRADCOM)

U. S. Army Aviation Training Library, Fort Rucker, Alabama 36360

1 ATTN: Buildings 5906-5907

Commander, U. S. Army Agency for Aviation Safety, Fort Rucker, Alabama 36362 1 ATTN: Librarian, Building 4905 Commander, USACDC Air Defense Agency, Fort Bliss, Texas 79916

1 ATTN: Technical Library

Commander, U. S. Army Engineer School, Fort Belvoir, Virginia 22060

1 ATTN: Library

Commander, U. S. Army Engineer Waterways Experiment Station, Vicksburg, Mississippi 39180

1 ATTN: Research Center Library

Commander, U. S. Army Fnvironmental Hygiene Agency, Edgewood Arsenal, Maryland 21010

1 ATTN: Chief, Library Branch

Technical Director, Human Engineering Laboratories, Aberdeen Proving Ground, Maryland 21005

1 ATTN: Technical Reports Office

Commandant, U. S. Army Quartermaster School, Fort Lee, Virginia 23801

1 ATTN: Quartermaster School Library

Commander, U. S. Army Radio Propagation Agency, Fort Bragg, North Carolina 28307

1 ATTN: SCCR-2

Naval Research Laboratory, Washington, D. C. 20375

1 ATTN: Dr. J. M. Krafft - Code 8430

General Dynamics, Convair Aerospace Division, P. O. Box 748, Fort Worth, Texas 76101

1 ATTN: Mfg. Engineering Technical Library

Chief of Naval Research, Arlington, Virginia 22217

1 ATTN: Code 471

Air Force Materials Laboratory, Wright-Patterson Air Force Base, Ohio 45433

minichter eine betreichte beiter beiter eine beiter beiter

2 ATTN: AFML/MXE/E. Morrissey

1 AFML/LC

1

AFML/LLP/D. M. Forney, Jr.

1 AFML/MBC/Stanley Schulman

National Aeronautics and Space Administration, Washington, D. C. 20546

1 ATTN: Mr. B. G. Achhammer

Mr. G. C. Deutsch - Code RW

National Aeronautics and Space Administration, Marshall Space Flight Center, Huntsville, Alabama 35812

1 ATTN: R. J. Schwinghamer, EH01, Director, M&P Laboratory

1 Mr. W. A. Wilson, EH41, Building 4612

- 1 Ship Research Committee, Maritime Transportation Research Board, National Research Council, 2101 Constitution Ave., N. W., Washington, D. C. 20418
- 1 Materials Sciences Corporation, Blue Bell Office Campus, Merion Towle House, Blue Bell, Pennsylvania 19422
- 1 The Charles Stark Draper Laboratory, 68 Albany Street, Cambridge, Massachusetts 02139

Wyman-Gordon Company, Worcester, Massachusetts 01601

1 ATTN: Technical Library

Lockheed-Georgia Company, 86 South Cobb Drive, Marietta, Georgia 30063

1 ATTN: Materials & Processes Engrg. Dept. 71-11, Zone 54

Director, Army Materials and Mechanics Research Center, Watertown, Massachusetts 02172

2 ATTN: DRXMR-PL

DRXMR-AG-MD

1 Author